

Product Change Notification

PCN No: 2007-02-20-01

Report Date: February 20, 2007

Subject: Alphanumerics New Firmware Version Release

List of New / Changed Products:

All the following Alphanumeric displays (and their variants):

| MOI Series | LCD0821 | |
|------------|----------|----------|
| LCD2041 | LK162-12 | LK202-25 |
| LK204-25 | LK402-25 | LK404-25 |
| VK162-12 | VK202-25 | VK204-25 |

Reason for Change:

A couple of firmware bug fixes and I2C implementation enhancement are incorporated in the existing firmware resulting to a firmware upgrade.

Product Change:

The following list of firmware changes are all effective on all the variants of the alphanumeric displays as stated under 'List of New / Changed Products'.

Firmware Changes:

| - 11 111 / W. G. C. W. Best | | |
|-----------------------------|----------------------|--|
| Display | New Firmware Version | |
| MOS Series | v5.4 | |
| X-Board | v5.4 | |
| LCD0821 | v5.8 | |
| LCD2041 | v5.8 | |
| VFD2041 | v5.8 | |

| LK162-12 | v5.4 |
|----------|------|
| VK162-12 | v5.4 |
| LK202-25 | v5.9 |
| VK202-25 | v5.8 |
| LK204-25 | v5.8 |
| VK204-25 | v5.8 |
| LK402-25 | v5.3 |
| LK404-25 | v5.4 |

New Released Firmware (released February 20, 2007):

- 1) In I2C, when a keypad key is pressed, two of the same values are read; the suggested fix for this before was to clear the key buffer every after read. There is no need for clearing the key buffer anymore, this bug is fixed.
- 2) In I2C, the module had problematic NAK acknowledgments; there were instances that the modules continue to ACK when the buffer is full. This bug is now fixed.

Contact Information:

Adam Lintott (Sales Manager): <u>alintott@matrixorbital.ca</u>

Reference Documents/Attachments:

Location: http://www.matrixorbital.ca/manuals/

Approvals:

Engineering: Larry Grieve (Engineering Coordinator)

Sales: Adam Lintott (Sales Manager)

Production: Mike McTavish (Production Manager)