

Product Change Notification

PCN No: 2006-12-07-01

Report Date: December 7, 2006

Subject: GLK12232-25-SM PCB 1.4 I2C Changes

Reason for Change:

The GLK12232-25-SM PCB 1.4 requires a special procedure in putting the module in I2C mode.

Product Change:

Instead of the procedure outlined on the GLK12232-25-SM PCB 1.4 manual for changing the module to I2C, the following steps are to be taken:

- 1) Solder both I2C pads (2 pads)
- 2) Solder left 232 pad (1 pad)
- 3) Lift pin 13 of the SP232AEN IC pin 13 is counted from top right counter clockwise as Figure 1 indicates (please note the board's orientation)

Please refer to the following figures:




Figure 1: GLK12232-25-SM PCB 1.4 I2C changes




Figure 2: Pads to Solder



Figure 3: Pin 13 of SP232AEN IC lifted

Contact Information:

Adam Lintott (Sales Manager): <u>alintott@matrixorbital.ca</u>

Reference Documents/Attachments:

Location: http://www.matrixorbital.ca/manuals/

Approvals:

| Documentation / Tech Support | Engineer | Engineer | Production | Sales |
|---------------------------------|--------------|----------------|---------------|--------------|
| Jon Klassen | Larry Grieve | James McTavish | Mike McTavish | Adam Lintott |